



A
PURAVANKARA HOME AT
SPARKLING SPRINGS

Pride of owning something precious

SPARKLING SPRINGS

AT THE PURVA SOUND OF WATER

Construction Updates

July 2023

Dear Esteemed Customer,

Greetings from Puravankara

It gives us immense pleasure to update you through this edition of Puravankara Newsletter and provide you with the latest information about your home in Sparkling Springs. As we move ahead, we at Puravankara sincerely thank you for your continual faith and trust reposed in the brand.

We are happy to inform you that the construction and infrastructure works at the site is progressing well. We thank you for your understanding that is a construction site with extensive debris, heavy vehicular movement, uneven surfaces and hence keeping in mind your safety, visits to this site is restricted. You may seek prior approval and we can accommodate the scheduled visit from your respective banker.

We are grateful for your kind cooperation.
Team Sparkling Springs





Sparkling Springs

Off Bannerghatta Main Rd, Bengaluru



Construction Updates

Overall view



Villa 03

- 1st to 2nd floor column work in progress.

PHASE 2



Villa 06

- Excavation & piling completed.

Actual site photograph



Villa 09

- Plinth completed.



Villa 10

- PCC for plinth beam completed.

Actual site photograph



Villa 12

- Plinth beam completed.



Villa 13

- PCC for plinth completed.

Actual site photograph



Villa 14

- PCC for plinth completed.



Villa 16

- 1st floor slab work in progress.



Villa 17

- Plinth beam completed.



Villa 18

- 1st floor beam shuttering work in progress.



Villa 19

- 1st floor to 2nd floor column work in progress.



Villa 21

- 1st to 2nd floor column work in progress.



Villa 22

- 1st to 2nd floor column work in progress.



Villa 23

- Excavation completed.

Actual site photograph



Villa 25

- First floor slab completed.



Villa 27

- 1st to 2nd floor column work in progress.



Villa 29

- Plinth beam reinforcement work in progress.



Villa 30

- Plinth beam completed.



Villa 31

- Plinth beam completed.



Villa 32

- First floor slab completed.



Villa 33

- PCC for plinth beam completed.



Villa 34

- Piling & excavation completed.



Villa 35

- Plie chipping work completed.



Villa 62

- First floor slab completed.



Villa 63

- First floor slab completed.



Villa 64

- First floor slab shuttering in progress.



Villa 65

- First floor slab shuttering in progress.



Villa 66

- Ground floor column casting in progress.



Villa 67

- 1st floor to 2nd floor column work in progress.



Villa 68

- Grade slab completed.



Villa 69

- Plinth beam completed.



Villa 71

- Plinth beam reinforcement work in progress.



Villa 73

- 1st floor slab completed.



Villa 74

- 1st floor slab completed.



Villa 75

- Plinth beam completed.



Overall view

Actual site photograph

PHASE 3

Villa 175

- Piling completed.



Villa 165

- Piling completed.



Actual site photograph

Contact us

Site Office :

Sparkling Springs

South Taluk, Kammanahalli Village , Begur Hobli Road,
Off Bannerghatta Main Rd, Bengaluru, Karnataka – 560076

Regional Office :

Puravankara Limited. #130/1, Ulsoor Road,
Bengaluru - 560 042

Email : crm@puravankara.com (Subject line – Project name/ unit number)

Call Us : +91 - 80-67724001 / 1 860 208 0000

Web : www.puravankara.com

OC Number :

JDBL (S)/ADBL/OC/11/2020-21